

DM CLEAN SUPER


ALKALINE CIP PRODUCT WITH EXTRA DEGREASING PROPERTIES




0,5 - 2 %



10 - 30 min




Rinse after use



40 - 80°C

Personal protection



First Aid



danger

H314 Causes severe skin burns and eye damage.

P280 Wear protective gloves/protective clothing/eye protection/face protection.

P260 Do not breathe dust/fume/gas/mist/vapours/spray.

P303 if on skin (or hair) remove immediately all contaminated clothing. Wash with plenty of soap and water.

P305 if in eyes rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do.

Continue rinsing immediately call a poison center or doctor/physician specific treatment.

P301+P330+P331+P310+P321 if swallowed rinse mouth do not induce vomiting.

Immediately call a poison center or doctor/physician specific treatment.

P264 Wash hands thoroughly after handling.