DM CLEAN ULTRA

STRONG ALKALINE CONCENTRATED CIP CLEANER









5 - 2 %

10 - 20 min

50 - 90°C

Personal protection







First Aid









H314 Causes severe skin burns and eye damage.
P260 Do not breathe gas, vapours, fume, spray.
P280 Wear Gloves, protective clothing, Safety glasses.
P301+P330+P331 if swallowed: rinse mouth. Do not induce vomiting.
P304+P340 if inhaled: remove victim to fresh air and keep at rest in a position comfortable for breathing.
P305+P351+P338 if in eyes: rinse cautiously with water for several minutes.
Remove contact lenses, if present and easy to do. Continue rinsing.
P310 immediately call a poison center or doctor/physician.
P501 dispose of contents/container to hazardous or special waste collection point, in accordance with local, regional, national and/or international regulation.





see MSDS